FERNALD COMMUNITY MEETING FEBRUARY 23, 1993

02/23/1993

DOE-FN 40 OVERHEADS PUBLIC



February 23, 1993

6:00 - 7:00 p.m. Exhibits

7:00 - 9:30 p.m. Group Meeting

Welcome / Public Issues________Ken Morgan

DOE Field Office Overview______Jim Fiore

New Acting Manager______Tom Rowland

FERMCO Update______Nick Kaufman

Waste & Materials Shipment /

Safe Shutdown_____Ray Hansen

Status of Cleanup______Jack Craig

Annual Site Environmental

Report for Calendar Year 1991_____Wally Quaider

Public Forum____Ken Morgan

U.S. EPA Comments
Ohio EPA Comments
FRESH Comments


Group Questions and Answers

Exhibits will reopen after the meeting.



FERNALD ENVIRONMENTAL MANAGEMENT PROJECT

- Siren System
- Public Water
- Community Environmental Course





FERNALD ENVIRONMENTAL MANAGEMENT PROJECT

- Oak Hills Award
- Risk Roundtable
- Fernald Advisory Committee



FERNALD ENVIRONMENTAL RESTORATION MANAGEMENT CORPORATION


Graphics 2009.21 2/93

FERMCO TRANSITION OBJECTIVES

- Listen, Learn, Refine Proposal Concepts
- Develop and Staff New Corporation
- Assume Contracts, Implement Prime Contract Provisions
- Determine Status of Systems, Procedures, Cost/Schedule/Regulatory Baselines
- Prepare to Manage to Regulations, DOE Orders, Commitments
- Create Support Climate with Employees, DOE, Regulators, Stakeholders
- Launch Improvement Initiatives

Graphics 2009.22 2/93

FERMCO CONCEPT OF ORGANIZATION



1

INITIATIVES

- Implement New ES&H Program
- Refocus Training
- Replan Space and Introduce New Systems
- Set Lab Strategy

INITIATIVES (Cont'd)

- Restore and Enhance CERCLA/RCRA Compliance; Develop Workarounds on Problems
- Initiate Strategic Regulatory Effort
- Accelerate Property Disposition
- Accelerate Waste Removal

FERMCO 5-YEAR VISION

- FERMCO Succeeding as a Team
- Worker and Public Health and Safety Protected
- One Year Ahead of Consent Agreement
- \$300 Million Saved Against 1992 Forecast
- Strategic Questions Answered
- New Approaches Succeeding
- Cooperation Among DOE, Regulators, Public, Officials

Graphics 2009.26 2/93

SAFE SHUTDOWN

- Production Equipment
- Materials Disposition
- Thorium
- Waste Shipments
- Other Waste Disposal

PRODUCTION EQUIPMENT

- Plant by Plant Assessment
 - Plant 4 Complete
 - Plant 1 in Progress
 - * Maintenance Scheduled for Utility Disconnects
 - * Hold-Up Material Removal Being Scheduled

MATERIALS DISPOSITION

Problem

- 20,000 Drums of Low Enriched Residues
 - NTS Requires "No Free-Standing Liquids"
 - Free Metals Must be Oxidized
 - Enriched Materials Cannot be Processed by Commercial Vendors

MATERIALS DISPOSITION (Cont'd)

Alternative Solutions:

- Lease/Contract Vendor Dryer/Oxidizer
- Lease/Contract Vendor Supercompactor
- Permit and Use Existing Rotary Kiln as Dryer/Oxidizer

MATERIALS DISPOSITION (Cont'd)

- Rotary Kiln
 - Will Enable 20,000 Drums of Waste to be Shipped to NTS

MATERIALS REMOVED FROM SITE:

 3,353 MTU Shipped Off-Site Since the Transfer

MTU = metric tonnes uranium

PLANNED MATERIALS REMOVAL FROM SITE (Cont'd)

- Complete Transfer of Remaining Army Metal
 - 1,012 MTU to Nevada (March August 1993)

Graphics 2009.11a 2/93

TI

FUTURE MATERIALS REMOVAL FROM SITE (Cont'd)

Future Sales

- Normal and Enriched RFP Mailed to 13 Companies 12/23/93 (Responses Received 2/8/93)
- Depleted RFP Mailed to 6 Companies 1/15/93 (Responses Due 3/7/93)

THORIUM

Inventory: 1,094 MT at Time of Transition

- 167 MT Shipped to NTS (Complete 9/30/92)
- 769 MT to be Shipped by End of FY'94

THORIUM (Cont'd)


Characterization, Stabilization, Overpacking and Shipments:

- Characterization:
 - Out of 10,551 Current Containers, 11 are RCRA (2 remain to be evaluated)
- Stabilization (T-2 Tank)
 - Sampling, Characterization, Preliminary Planning Ongoing

THORIUM (Cont'd)

- Overpacking
 - Buildings 64 and 68 Completed in FY'92
 - Building 67 to be Completed by 2/28/93 Status as of 1/31/93:
 - 2,910 Containers Overpacked
 - 3,094 to be Overpacked
 - Building 65 Scheduled for Fall of '93

WASTE SHIPMENTS TOTAL DRUM EQUIVALENT SHIPMENTS



WASTE SHIPMENTS

- FY'93 Goal: 117,000 DEs
- Accelerated Goal FY'93 181,000

OTHER WASTE DISPOSAL

Contracts to Ship Residues and Metal

- Scrap Metal
 - Vendor Mobilized
 - Shipments Started Week of 2/8/93
- Drummed Residues
 - Vendor Mobilizing
 - Shipments to Start Week of 2/22/93

COMMUNITY MEETING

Update of RI/FS and Removal Action Activities

- RI/FS Status
- Removal Actions
 - Pit 5


- RI/FS Status
- Removal Actions
 - Inactive Flyash Pile

- RI/FS Status
 - Accelerated Decontamination and Decommissioning
- Removal Actions
 - Plant 1 Ore Silos
 - Plant 1 Pad Upgrade

- RI/FS Status
- Removal Actions
 - Bentonite Effectiveness
 - Decant Sump Tank


- RI/FS Status
- Removal Actions
 - South Plume

SOUTH GROUNDWATER CONTAMINATION PLUME REMOVAL ACTION #3





REMOVAL ACTION #1 CONTAMINATED WATER BENEATH FEMP BUILDINGS



PLANT 8 VOC TREATMENT SYSTEM

OBJECTIVE:

 Minimize the Potential for Uranium-Contaminated Groundwater to Infiltrate the Underlying Aquifer from Perched Water Zones Located Beneath Some Production Buildings.

BENEFIT:

• Minimize the Potential for Movement of Contaminated Water in These Perched Water Zones.

ACTIVITIES:

- Plant 8 Treatment System Continues to Remove Volatile Organic Compounds Prior to Treatment for Removal of Uranium and Subsequent Discharge to River.
- Pumping of Perched Groundwater in Progress at all Identified Locations. Pumping to Continue in This Manner Until Advanced Wastewater Treatment System is Operational in 1994.

SCHEDULE:

Pumping Ongoing Through March 30, 1994



REMOVAL ACTION #2 WASTE PIT AREA RUNOFF CONTROL

OBJECTIVE:

 Reduce Potential Groundwater Contamination from Contaminated Stormwater Runoff.



- Reduce or Mitigate the Release of Uranium and Other Contaminants to Paddy's Run.
- Mitigate the Potential for Contaminants from Surface Water from Reaching the Underlying Aquifer.

ACTIVITIES:

- Collection of Runoff in the Waste Pit and Adjacent Areas Through the Installation of Trenches and Dikes.
- Treatment of Runoff in Existing FEMP Wastewater Treatment Facilities.

SCHEDULE:


Project Completed July 30, 1992. System Operational.

Graphics 1928.2 12/92

Fernald Environmental Management Project



REMOVAL ACTION #3 SOUTH GROUNDWATER CONTAMINATION PLUME



PART 2 - PUMP AND DISCHARGE SYSTEM

OBJECTIVE:

 Protect Public Health by Limiting Access to the Use of Uranium-Contaminated Groundwater in an Area South of the Fernald Site. The Removal Action is Broken into Five Parts.

BENEFITS:

• 1) Provide Alternate Water Supply to Affected Industry; 2) Extract and Pump Contaminated Groundwater Back to the Fernald Site for Monitoring, Possible Treatment, and Discharge to the Great Miami River; 3) Construction and Operation of Interim Advanced Wastewater Treatment System; 4) Groundwater Modeling and Controls to Prevent the Use of Contaminated Groundwater, and 5) Additional Groundwater Investigations in the Vicinity of the South Plume.

ACTIVITIES:


• Pipeline Construction Activities in Progress.

SCHEDULE:

Part 1 was Completed on Schedule in December 1992 Part 2 on Schedule for Completion in August 1993 Part 3 is Complete and Operational Parts 4 and 5 are Ongoing

(1)





OBJECTIVE:

 Reduce Chronic Radon Emissions from Silos 1 and 2.

BENEFITS:

- Decrease, Mitigate, or Otherwise Control the Threat of a Release in the Event of a Silo Dome Collapse.
- Reduce Potential Radon Exposure of Both On-Site and Off-Site Personnel.

ACTIVITIES:

 This Removal Action Consisted of Placing Bentonite Clay Over the Top of the Residues Contained in Each Silo.

SCHEDULE:

This Removal Action was Completed in November 1991. DOE is Proceeding with Statistical Evaluation of Available Data to Demonstrate the Effectiveness of the Bentonite. This Data will be Provided to the U.S. EPA as it Becomes Available.




 Reduce the Potential for Leakage of Contaminated Water into Surrounding Soils.

BENEFIT:

 Liquid was Analyzed at Off-Site Laboratory to Determine Proper Treatment and Disposition.

ACTIVITIES:

 Approximately 8,000 Gallons of Water was Removed, Analyzed, and Treated Through Existing Wastewater Treatment Systems at Fernald Prior to Discharge to the Great Miami River. The K-65 Decant Sump Tank was Used to Collect and Store Liquid that Drained from the K-65 Silos as the Slurried Material Settled.




LOCATION OF K-65 DECANT SUMP TANK

SCHEDULE:

This Removal Action was Completed in April 1991

Graphics 1928.5 12/92





 Eliminate the Potential for Airborne Emissions Due to Wind Erosion from the Fernald Site Waste Pit Area.

BENEFITS:

 Mitigate Source of Potential Airborne Fugitive Dust Emissions.

ACTIVITIES:

 A Mound of Approximately 4,800 Square Feet of Dried Radioactive Waste was Submerged Below the Water Line and Distributed Evenly Below the Surface of the Water. The Mound Contained Process Residues, Asbestos, Depleted Slag, Green Salt, and Filter Cake from Past Operations at the Fernald Site.

SCHEDULE:

This Removal Action was Completed in December 1990



REMOVAL ACTION #7 PLANT 1 PAD CONTINUING RELEASE



OBJECTIVE:

Upgrade Existing Plant 1 Pad Plus Provide 80,000
 Square Feet Additional Pad Area.

BENEFIT:

 Control the Potential for Migration of Contaminants from Materials Stored on the Pad into Surrounding Environmental Media.

ACTIVITIES: Three Phase Approach:

- Phase I- Implement Run-on/off Control Measures.
- Phase II- Installation of 80,000 Square Feet of New Covered and Controlled Concrete Storage Pad.
- Phase III- Upgrade 375,000 Square Feet of the Existing Plant 1 Storage Pad, Enclose 22,000 Square Feet Beneath a Sprung Structure.

SCHEDULE:

Phases I and II are Complete
Phase III is on Schedule for Completion by February 19, 1995





Prevent Unauthorized Intrusion/Access into Radiological Surface Soil Contamination Area.

BENEFITS:

• Minimization of Potential Risk to Human Health.

ACTIVITIES:


This Removal Action Consisted of Posting of Warning Signs and Installing a Chain Barrier Around the Perimeter of the Inactive Flyash Pile/Other South Field Disposal Areas.

SCHEDULE:

This Removal Action was Completed in December 1991



REMOVAL ACTION #9 REMOVAL OF WASTE INVENTORIES LOW LEVEL WASTE MANAGEMENT



OBJECTIVE:

 Off-Site Disposition of Drummed Low Level Waste (LLW).

BENEFIT:

 Reduces Environmental Risk Due to the Potential of LLW Materials Stored in Containers to Migrate into the Air and Surface Waters, Reduces Worker Exposure to Hazardous Substances, Shifts Manpower Focus to Remedial Tasks.

ACTIVITIES:

Encompass Existing Waste Shipping and Management Procedures for Drummed LLW from Backlog and Construction Wastes.

SCHEDULE:


Submitted Updated Procedures June 1992

Submit Updated Procedures June Annually

Ongoing Removal of Waste Inventories Through September 30, 1997



REMOVAL ACTION #9 REMOVAL OF WASTE INVENTORIES THORIUM MANAGEMENT



OBJECTIVE:

 Overpacking and Off-Site Removal of Drummed Thorium Material.

BENEFIT:

 Mitigates Potential for Releases from the Drummed Thorium Material, Reduces Stored Waste Inventories and Worker Exposures.

ACTIVITIES:

 Encompass Existing Shipping and Management Procedures for Thorium Materials that are Ready to be Shipped and those which Require Overpacking for the Off-Site Disposition, Approximately 10,600 Drum Equivalents.

SCHEDULE:

Submitted Updated Procedures June 1992

Submit Updated Procedures June Annually

Ongoing Removal of Waste Inventories Through September 30, 1994

Graphics 1928.9 12/92



REMOVAL ACTION #10 ACTIVE FLYASH PILE CONTROLS



OBJECTIVE:

• Control Wind and Water Erosion of Active Flyash Pile.

BENEFITS:

- Minimize Wind and Surface Water Erosion.
- Reduce Fugitive Dust Emissions.
- Protective of Human Health and Safety.

ACTIVITIES:

 This Removal Action Consisted of a Combination of Control Measures to Minimize Fugitive Dust Emissions and Stormwater Runoff. A Silt Fence was Installed Around the Base of the Pile to Mitigate Stormwater Runoff and Wind Barriers were put in Place to Mitigate Wind Erosion. Minor Grading and Compaction were Conducted and a Chemical Spray was Applied to the Surface to Provide Stabilization.


SCHEDULE:

This Removal Action was Completed in June 1992

Graphics 1928.10 12/92



REMOVAL ACTION #11 PIT 5 EXPERIMENTAL TREATMENT FACILITY



OBJECTIVE:

 Reduce the Spread of Contamination and Exposure of Personnel to ETF Wastes.

BENEFITS:

- Reduce or Mitigate the Release of Waste Materials Contained in the ETF to the Surrounding Area.
- Reduce or Mitigate the Potential for Exposure of Personnel through Removal of the ETF.

ACTIVITIES:

- Remove and Dispose of the Vegetation Surrounding the ETF.
- Collect, Containerize, and Store Waste Material Contained Within the ETF Structure.
- Collect, Containerize, and Store Filter Bed and ETF Wooden Structure.
- Sample and Analyze the Soil Affected by the ETF.


SCHEDULE:

This Removal Action was Completed in March 1992

Graphics 1928.11 12/92



REMOVAL ACTION #12 SAFE SHUTDOWN



OBJECTIVE:

 Removal and Disposition of Uranium and Process Materials from Fernald Site Buildings.

BENEFITS:

 Eliminates Source Term for Further Environmental Releases. Enhances ALARA Goals. Provides Necessary Preliminary Step for Preparation of the Systems for Subsequent Remedial Activities.

ACTIVITIES:

 Document Ongoing Shutdown Activity which will Remove Uranium and Other Process/Raw Materials from Equipment and Lines in Areas of Formerly Used Processing Equipment in Plants 1, 2/3, 4, 5, 6, 9 and the Pilot Plant. Systematic, Plant by Plant Implementation of Safe Shutdown and Incorporation of Results Into OU3 RI/FS.

SCHEDULE:

Submitted Updated Procedures June 1992


Submit Updated Procedures June Annually

Ongoing Safe Shutdown Implementation Period Through September 30, 1995

Graphics 1928.12 12/92



REMOVAL ACTION #13 PLANT 1 ORE SILOS



OBJECTIVE:

• Dismantle the Plant 1 Ore Silos and Support Structure.

BENEFITS:

- Eliminates Threat of Additional Material Releases.
- Eliminates Safety Hazard Due to Structural
 Deterioration of the Silos and Supporting Structure.

ACTIVITIES:


 Remove, Containerize, Characterize, and Dispose of the Material Identified to Exist in Eight of the Silos. All 14 Silos at Plant 1 will be Dismantled Under this Removal Action.

SCHEDULE:

Submitted Final Work Plan to U.S. EPA July 1992 Initiated Field Activities October 1992 Complete Removal Action December 1994



REMOVAL ACTION #14 CONTAMINATED SOILS ADJACENT TO SEWAGE TREATMENT PLANT INCINERATOR



OBJECTIVE:

 To Address Contaminated Soils with Elevated Levels of Uranium.

BENEFIT:

 Mitigates the Potential for Migration of Contamination.

ACTIVITIES:

 Remove and Dispose of Contaminated Soils in the Vicinity of an Out-of-Service Solid Waste Incinerator at the Sewage Treatment Plant.

SCHEDULE:

Completed Phase I (Walkover Survey) August 1992

Completed Phase II (Excavation and Verification Sampling) October 1992

Complete Phase III (Submit Interim Reports) April 1993

Phase IV (Submit Evaluation for Further Action) July 1993

Graphics 1928.14 12/92



REMOVAL ACTION #15 SCRAP METAL PILES



OBJECTIVE:

 Removal of Low-Level Radioactive Waste Scrap Metal Off-Site.

BENEFIT:

 Eliminate Potential Air Emission Source and Reduce Releases to Surge Lagoon and Great Miami River by Eliminating Source Contamination to Surface Water Runoff.

ACTIVITIES:

- Off-Site Removal, Treatment, and Disposition of 3,000 Tons of Recoverable Scrap Metal.
- Material Includes Approximately 1300 Tons of Scrap Copper and Other Small Metal Piles.

SCHEDULE:

Submitted Final Work Plan to U.S. EPA June 1992

Complete Phase I March 1994


Complete Phase II May 1995

Graphics 1928.15 12/92



REMOVAL ACTION #16

COLLECT UNCONTROLLED PRODUCTION AREA RUNOFF (NORTHEAST)



OBJECTIVE:

• Collect Uncontrolled Process Areas Runoff.

BENEFITS:

- Reduce or Mitigate the Release of Uranium and Other Contaminants to Paddy's Run.
- Mitigate Contaminants from Surface Water to Underlying Aquifer.

ACTIVITIES:

 Redirection of Subdrainage Areas and Collection of Runoff from Perimeter of Process Area.

SCHEDULE:

Submitted Work Plan to U.S. EPA March 2, 1992 Complete Removal Action August 30, 1993

Graphics 1928.16 12/92



REMOVAL ACTION #17 IMPROVED STORAGE OF SOIL AND DEBRIS



OBJECTIVE:

• Install Tension Support Structures and Implement Controls to Integrate and Improve Soil & Debris Storage Facilities.

BENEFIT:

 Minimize Potential Contaminant Migration from Specific Storage Areas.

ACTIVITIES:


- 1 Define Soil and Debris Waste Streams.
- 2 Revise Existing Procedures for Management and Control of Waste Streams.
- 3 Identify Suitable Areas for Storage of Soil and Debris Waste Streams.
- 4 Develop Technology or Engineering Approaches for Handling of Waste Streams.
- 5 Evaluate the Engineering Approaches Considered with Respect to Appropriate ARARs.
- 6 Establish Current and Future Policy with Respect to Soil and Debris Waste Streams for the FEMP.

SCHEDULE:

Submitted Final Work Plan to U.S. EPA August 1992 Provided Phase I Storage Upgrades for Existing Piles July 1992 Complete Construction (Storage Facilities) March 1995

Graphics 1928.17 12/92





 Control Surface Emission of Radionuclide Contamination from Waste Pit 5.

BENEFITS:

 Reduce or Mitigate Worker Exposure and Exposure to Off-Site Residents Due to Airborne Radionuclide Contamination.

ACTIVITIES:

- Evaluated Alternatives for Emission Control and Selected Preferred Approach.
- Prepared Work Plan Using Preferred Alternative (Dredging) and Obtained EPA Approval.


SCHEDULE:

This Removal Action was Completed in December 1992

Graphics 1928.18 12/92



REMOVAL ACTION #19 DECONTAMINATION AND DISMANTLING OF PLANT 7



OBJECTIVE/BENEFIT:

Plant 7 is an Activity to Support the DOE Integrated Technology Demonstration Program and its D&D will also Serve as a Pilot Program for Future Remedy of the Site.

ACTIVITIES:

Decontaminating and Dismantling Operations will be Conducted. After Equipment Removal, the Building Demolition and Removal will begin. The Major Activities Anticipated Include: 1) Relocation of Stored Drummed Material, Combustibles, or Hazardous Waste; 2) Removal of Asbestos Insulated Pipes; 3) Provision for Surface Decontamination of Interior Components; 4) Termination of Utility Services; 5) Removal of the Transite Surface Panels; and 6) Dismantling of the Structural Steel.


SCHEDULE:

Submit Draft Work Plan to U.S. EPA April 1993

Graphics 1928.19 12/92



REMOVAL ACTION #20 STABILIZATION OF UNH INVENTORIES



OBJECTIVE:

Remove and Prepare for Safe Storage 220,000
 Gallons of Acidic UNH Currently Stored in 21
 Tanks in and Around Plant 2/3.

BENEFIT:

Mitigate Potential Releases to Environment.

ACTIVITIES:

 Neutralize Solutions, Precipitate the Material, Filter the Precipitate, and Package the Resulting Filter Cake in Double Containment for Safe Storage.

SCHEDULE:


Completed Systems Integrity Testing February 1992

Commenced Processing Material July 1992

Complete Processing Material Spring 1993

Graphics 1928.20 12/92





• Eliminate the Potential for Release of Radioactive Material to the Environment from the Silo 3 Dust Collector and Hopper Assembly.

BENEFIT:

 All Pathways are Permanently Sealed to Prevent the Release of Silo 3 Contents to the Atmosphere.
 Eliminated the Source of Potential Airborne
 Emissions.

ACTIVITIES:

 The Three-Piece Assembly was Removed from Atop the Silo Dome and Lowered Directly into a Sea/Land Container for Disposal. Piping and Associated Equipment Originally Used to Place Waste in the Silo were also Removed and Prepared for Shipment.


SCHEDULE:

This Removal Action was Completed in January 1992.

Graphics 1928.21 12/92



REMOVAL ACTION #22 WASTE PIT AREA CONTAINMENT IMPROVEMENT



OBJECTIVE:

 Minimize the Potential for Wind or Water Erosion of Contaminated Materials from Access Roads and Exposed Surfaces in the Waste Pit Area.

BENEFIT:

 Mitigate Sources of Potential Airborne Dust Emissions and Contaminated Surface Water Runoff.

ACTIVITIES:


 This Removal Action will Include Revegetation (Seeding) of the Pit Area for Erosion Control, and Regrading of Some Existing Stormwater Ditches in the Pit Area to Promote Positive Drainage.

SCHEDULE:

Revised Work Plan Submitted to U.S. EPA in November 1992

Graphics 1928.22 12/92





 Removal and Disposition of Isolated Areas of Radiological Surface Contamination in the Inactive Flyash Pile/Other South Field Disposal Areas.

BENEFIT:

• Mitigate Potential Migration of Contaminants.

ACTIVITIES:


 A Small Amount of Debris Including Soil and Transite Material was Removed from the Inactive Flyash Pile and Placed in Approprlate Containers for Storage Pending Final Disposition.

SCHEDULE:

This Removal Action was Completed in June 1992

Graphics 1928.23 12/92





 Remove the Sump and its Liquid and Sludge Containing High Concentrations of Metals.

BENEFIT:

 Mitigate Source of Potential Environmental Releases.

ACTIVITIES:

 Pump-out Accumulated Liquid and Sludges, Removal of the Sump Tank, Identification and Removal of Contaminated Soils Resulting from its Operation. A Total of 635 Gallons have been Pumped Out in Four Separate Operations So Far.


SCHEDULE:

Submitted Draft Final Work Plan to U.S. EPA on October 14, 1992

Graphics 1928.24 12/92



REMOVAL ACTION #25 NITRIC ACID TANK CAR AND AREA



OBJECTIVE:

 Remove Residual Contents Followed by Decontamination and Disposition of the Tank Car.

BENEFITS:

- Mitigate Source of Potential Contamination
 Releases to the Environment.
- Initiate RCRA Closure Activities for Designated HWMU.

ACTIVITIES:

 Remove Residual Contents and Decontaminate and Disposition the Tank Car, Characterize Soils in the Area for Contaminants Related to the Tank Car and Determine if Subsequent Soil Excavation will be Required.


SCHEDULE:

Submitted Work Plan to U.S. EPA on October 30, 1992 Final Draft Work Plan Submitted to U.S. EPA in December 1992

Graphics 1928.25 12/92



REMOVAL ACTION #26 ASBESTOS REMOVALS (ASBESTOS PROGRAMS)



OBJECTIVE:

 Manage Ongoing Asbestos Abatement Activity at the Fernald Site.

BENEFIT:

- Mitigate the Potential for Contaminant Release and Migration.
- Reduce Potential for Worker Exposure to Respirable Asbestos.

ACTIVITIES:

- Document Existing Conditions.
 Ongoing Abatements Include:
 - In-Situ Repairs
 - Encasement
 - Encapsulation
 - Removal

SCHEDULE:

Submit Annual Work Procedures to EPA Annually Each May

Graphics 1928.26 12/92



REMOVAL ACTION #27

MANAGEMENT OF CONTAMINATED STRUCTURES AT FERNALD



OBJECTIVE:

 Establish a Broad-based Removal Action to Support the Implementation of Clean-up Actions at Fernald's Contaminated Facilities.

BENEFIT:

 Mitigate the Potential Threat to Human Health and Environment.

ACTIVITIES:

 Submit Engineering Evaluation/Cost Analysis (EE/CA) to Support Proposed Removal Actions for Managing Contaminated Structures/Facilities.

SCHEDULE:

Submitted EE/CA to U.S. EPA December 16,1992

Graphics 1928.27 12/92